

INSP	TASK#	DESCRIPTION	DISPOSITION	EXP DATE	ATA	COLOR	COMPLETED DATE
LUB	122232-LUB-10000-1	MAIN LANDING GEAR - LUBRICATION OF HINGE POINTS OF MAIN LANDING GEAR LEG AND ASSOCIATED BRACE ASSEMBLIES	Service	27-May-25	12		29-May-25
LUB	122232-LUB-10005-1	MAIN LANDING GEAR DOORS - LUBRICATION OF MAIN LANDING GEAR DOORS, INCLUDING FOLDING DOORS	Service	27-May-25	12		29-May-25
LUB	122232-LUB-10010-1	NOSE LANDING GEAR - LUBRICATION OF HINGE POINTS OF NOSE LANDING GEAR LEG AND ASSOCIATED BRACE ASSEMBLIES	Service	27-May-25	12		29-May-25
LUB	122232-LUB-10015-1	NOSE LANDING GEAR DOORS - LUBRICATION OF NOSE LANDING GEAR DOORS	Service	27-May-25	12		29-May-25
RAI	256000-RAI-10000-1	CABIN FLASHLIGHTS - REMOVAL OF CABIN FLASHLIGHTS FOR BATTERY DISCARD AND SUBSEQUENT OPERATIONAL TEST (NON-CFR)	Service	2-Jul-23	25		
GVI	ZL-633-GVI-10000-1	RIGHT WING OUTBOARD TRAILING EDGE - GENERAL VISUAL INSPECTION OF OUTBOARD TRAILING EDGE	Service	6-Apr-24	57		13-Jun-25
DVI	271000-DVI-10000-2	AILERON TAB CONTROL - DETAILED VISUAL INSPECTION OF AILERON TAB DUAL LOAD PATH LINKAGE (LEFT AND RIGHT) FOR CONDITION AND SECURITY	Service	12-Apr-24	27		19-Jun-25
GVI	522202-GVI-10000-1	PILOT EMERGENCY EXIT HATCH - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON INTERNAL SURFACE OF FLIGHT COMPARTMENT OVERHEAD HATCH	Service	2-Oct-24	52		23-Jul-25
DVI	523102-DVI-10000-1	CARGO DOOR - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON INTERNAL SURFACE OF LH FWD CARGO DOOR (CPCP)	Service	1-Oct-24	52		22-Jul-25
DVI	523104-DVI-10000-1	CARGO DOOR - DETAILED VISUAL INSPECTION ON OUTER SKIN OF LH FWD CARGO DOOR AROUND THE PIANO HINGE	Service	1-Oct-24	52		22-Jul-25
DVI	531106-DVI-10000-1	FUSELAGE NOSE SECTION - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION UNDER DME/2 ANTENNA ON EXTERNAL SURFACE OF LOWER LOBE AFT PANEL LH (CPCP)	Service	5-Apr-24	53		9-Jul-25
DVI	531112-DVI-10000-1	FUSELAGE NOSE SECTION (FRAME 7 TO 13) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON LH AND RH LOWER LOBE AFT PANEL BELOW THE FLOOR FROM FRAME 7 (STATION 4426) TO FRAME 13 (STATION 5707) INTERNAL SURFACE	Service	9-Oct-24	53		4-Jul-25
DVI	531126-DVI-10000-1	NODE 5 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON NODE 5 INTERNAL SURFACE	Service	24-Nov-24	53		4-Jul-25
DVI	531129-DVI-10000-1	NODE 6 AND 7 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON NODE 6 AND 7 -FRAME AND SPLICE (L FITTING)	Service	16-Nov-24	53		4-Jul-25
DVI	531130-DVI-10000-1	NODE 3 AND POSTS NODES 1-5,2-6,3-7 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON NODE 3 AND POSTS BETWEEN NODES 1-5, 2-6, 3-7 LH AND RH SIDE (CPCP)	Service	16-Nov-24	53		4-Jul-25
DVI	531131-DVI-10000-1	COCKPIT WINDOW INSTALLATION - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON NODE 1 AND 2 (LH AND RH SIDE) OF COCKPIT WINDOW INSTALLATION	Service	16-Nov-24	53		4-Jul-25
DVI	531132-DVI-10000-1	COCKPIT WINDOW INSTALLATION - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON NODES 4, 8 AND SILLS BETWEEN NODES 1-2, 2-4, 5-6, 6-7, 7-8 LH AND RH SIDE OF COCKPIT WINDOW INSTALLATION	Service	5-Feb-24	53		4-Jul-25
GVI	531134-GVI-10000-1	FWD PRESSURE BULKHEAD - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON FWD PRESSURE BULKHEAD - FWD SURFACE	Service	2-Oct-24	53		2-Jul-25
DVI	533101-DVI-10000-1	CROWN PANEL - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION UNDER ANTENNAS ON EXTERNAL SURFACE OF CROWN PANEL BETWEEN FR 13 AND FR 23 (CPCP)	Service	12-May-24	53		10-Jul-25
DVI	533104-DVI-10000-1	LOWER PANEL - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION UNDER ANTENNAS ON EXTERNAL SURFACE OF LOWER PANEL BETWEEN FR 13 AND FR 23 AND BETWEEN STR 17 LH AND RH (CPCP)	Service	12-May-24	53		9-Jul-25
DVI	533105-DVI-10000-1	FORWARD CENTER SECTION (FR 13 TO 17) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON CREASE BEAM LH AND RH BETWEEN FRAME 13 AND FRAME 17 AT STRINGER 14 (CPCP)	Service	5-Apr-24	53		18-Jul-25

DVI	533105-DVI-10010-1	FORWARD CENTER SECTION (FR 17 TO 23) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON CREASE BEAM LH AND RH BETWEEN FRAME 17 TO FRAME 23 (CPCP)	Service	5-Apr-24	53		18-Jul-25	
DVI	533106-DVI-10000-1	WINDOW FRAMES (FR 17 TO 23) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON WINDOW FRAMES BETWEEN FR 17 AND FR 23 LH AND RH (INCLUDING EMERGENCY EXITS) - INTERNAL SURFACE. NOTE: BORESCOPE INSPECTION (SDI) FOR THE PORTION OF THE FRAME NEXT TO THE RUBBER JOINT. (CPCP)	Service	6-Oct-24	53		21-Jul-25	
GVI	533125-GVI-10000-1	LOWER SIDE PANELS - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON LOWER LH AND RH SIDE PANELS BETWEEN FR 13 AND FR 23 AND BETWEEN STR 13 AND STR 17 - INTERNAL SURFACE NOTE: PAY PARTICULAR ATTENTION TO STRINGERS (CPCP)	Service	15-Oct-24	53		14-Jul-25	
DVI	533300-DVI-10000-1	FUSELAGE SECTION 13 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON SEAT TRACKS BETWEEN FR13 AND FR17A (CPCP)	Service	5-Apr-24	53		4-Jul-25	
DVI	533300-DVI-10010-1	FUSELAGE SECTION 13 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON SEAT TRACKS BETWEEN FR17A AND FR23 (CPCP)	Service	5-Apr-24	53		4-Jul-25	
DVI	533701-DVI-10010-1	FUSELAGE FORWARD SECTION - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON ROLLER GUIDES (4 PLACES), HINGE AND LATCH FITTINGS (3 PLACES) OF CARGO DOOR	Service	1-Oct-24	53		14-Jul-25	
DVI	535121-DVI-10000-1	SPAR BULKHEAD - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON FRONT AND REAR SPAR MAIN FRAMES AT FR 25 AND FR 27 BETWEEN STR 14 LH AND RH SIDE - INTERNAL SURFACE (CPCP)	Service	29-Sep-24	53		21-Jul-25	
GVI	535125-GVI-10000-1	KEEL BEAM BETWEEN FR 25 AND FR 27 - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON KEEL BEAM BETWEEN FR 25 AND FR 27 - EXTERNAL SURFACE. NOTE: PAY PARTICULAR ATTENTION TO INTERNAL SURFACE OF LOWER PLATE. (CPCP)	Service	13-Nov-24	53		17-Jul-25	
DVI	535128-DVI-10000-1	FUSELAGE CENTER SECTION - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON FORWARD CORNER OF MAIN LANDING GEAR WHEEL WELL	Service	5-Apr-24	53		17-Jul-25	
DVI	535150-DVI-10000-1	FUSELAGE CENTER SECTION - DETAILED VISUAL INSPECTION FOR CRACK DETECTION OF FLOOR BEAM AT FRAME 26 - AROUND CUT-OUTS FOR ELECTRICAL/ELECTRONICS COOLING DUCTS AND HYDRAULIC PIPES INSTALLATION	Service		53		21-Jul-25	
DVI	535300-DVI-10000-1	FUSELAGE SECTION 15 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON SEAT TRACKS BETWEEN FR 23 AND FR 29 (CPCP)	Service	5-Apr-24	53		4-Jul-25	
DVI	535701-DVI-10000-1	MAIN LANDING GEAR TRUNNION SUPPORT - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON MAIN LANDING GEAR SUPPORT STRUCTURES BETWEEN FUSELAGE MAIN FRAMES 25 AND 27 (CPCP)	Service	13-Oct-24	53		17-Jul-25	
DVI	536103-DVI-10000-1	FUSELAGE REAR SECTION - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION UNDER VHF/2 ANTENNA ON LOWER PANEL FROM FR 29 TO FR 42 AND BETWEEN STR 17 LH AND RH - EXTERNAL SURFACE (CPCP)	Service	7-Oct-24	53		9-Jul-25	
GVI	536108-GVI-10000-1	FLOOR BEAM AND STANCHIONS - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON FLOOR BEAM AND STANCHIONS BETWEEN FR 29 AND FR 42 - INTERNAL SURFACE (CPCP)	Service	5-Apr-24	53		16-Jul-25	
DVI	536112-DVI-10010-2	FUSELAGE REAR CENT SECTION (FR 34 TO 39) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON CREASE BEAM LH AND RH AT STRINGER 14 FROM FRAME 34 (STATION 16487) TO FRAME 39 (STATION 18149) (CPCP)	Service	5-Apr-24	53		17-Jul-25	
DVI	536112-DVI-10020-2	FUSELAGE REAR CENT SECTION (FR 39 TO 44) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON CREASE BEAM LH AND RH AT STRINGER 14 FROM FRAME 39 (STATION 18149) TO FRAME 44 (STATION 20425) (CPCP)	Service	5-Apr-24	53		17-Jul-25	
DVI	536113-DVI-10000-1	WINDOW FRAMES (FRAME 29 TO 35) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON INTERNAL SURFACE OF WINDOW FRAMES BETWEEN FR 29 AND FR 35 LH AND RH SIDE (CPCP)	Service	7-Oct-24	53		21-Jul-25	
GVI	536119-GVI-10000-1	FRAMES 36,37,38,39 - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON FRAMES 36,37,38,39 LH AND RH SIDES BETWEEN STR 13 LH AND 13 RH (CPCP)	Service	5-Apr-24	53		18-Jul-25	

DVI	536300-DVI-10000-1	FUSELAGE SECTION 16 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON SEAT TRACKS BETWEEN FR 29 AND FR 36 (CPCP)	Service	5-Apr-24	53		4-Jul-25
DVI	536300-DVI-10020-1	FUSELAGE SECTION 16 - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON SEAT TRACKS BETWEEN FR 36 AND FR 44 (CPCP)	Service	5-Apr-24	53		21-Jul-25
DVI	536702-DVI-10010-1	SERVICE DOOR - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON: -HINGE FITTINGS (2 PLACES) -SHOOT BOLT FITTINGS (5 PLACES) INSTALLED ON SURROUND OF RH SERVICE DOOR	Service	1-Oct-24	53		21-Jul-25
DVI	538111-DVI-10000-1	AFT PRESSURE BULKHEAD FWD SURFACE - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON AFT PRESSURE BULKHEAD ASSY FWD SURFACE (CPCP)	Service	30-Jul-24	53		10-Jul-25
DVI	538112-DVI-10010-1	AFT PRESSURE BULKHEAD AFT SURFACE - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON AFT PRESSURE BULKHEAD AFT SURFACE (CPCP)	Service	30-Sep-24	53		10-Jul-25
DVI	538121-DVI-10000-2	FUSELAGE TAIL SECTION (FRAMES 43 TO 47) - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON FRAMES 43,44,45,46,47 LOWER SEGMENT BETWEEN STR 7 LH AND 7 RH (CPCP)	Service	30-Sep-24	53		7-Jul-25
GVI	538152-GVI-10000-1	GENERAL VISUAL INSPECTION FUSELAGE TAIL SECTION	Service	28-Apr-24	53		14-Jul-25
DVI	562101-DVI-10000-2	CABIN WINDOWS - DETAILED VISUAL INSPECTION OF CABIN WINDOWS (INCLUDING EMERGENCY EXITS) FOR DAMAGE DETECTION	Service	15-Dec-24	56		21-Jul-25
DVI	571213-DVI-10000-1	FRONT SPAR OF WING CENTER BOX - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON WING CENTER BOX FRONT SPAR BETWEEN RIB 13 LH AND RIB 13 RH, INCLUDING ALL FITTINGS AND BRACKETS FITTED ON THE SPAR (CPCP)	Service	13-Oct-24	57		27-Jun-25
DVI	571220-DVI-10000-1	CENTER WING BOX - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON CENTER WING BOX REAR SPAR (INCLUDING ALL FITTINGS AND BRACKETS) BETWEEN RIB 13 LH AND RIB 13 RH (CPCP)	Service	13-Oct-24	57		27-Jun-25
GVI	571406-GVI-10000-1	CENTER WING BOX - GENERAL VISUAL INSPECTION FOR CORROSION DETECTION ON HOUSINGS OF UPPER SKIN ACCESS DOORS BETWEEN RIBS 4 AND 5 (LH AND RH) AND BETWEEN RIBS 1 AND 2 (LH ONLY). (CPCP)	Service	19-Apr-24	57		8-Jun-25
DVI	571407-DVI-10000-1	FUEL PUMP CUT-OUT - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON WING LOWER SKIN AT FUEL PUMP CUT-OUT BETWEEN RIB 4 AND RIB 5 - EXTERNAL SURFACE (CPCP)	Service	6-Oct-24	57		25-Jun-25
DVI	571409-DVI-10000-1	LOWER SURFACE PANELS - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON LOWER SKIN AT JUNCTION WITH FRONT SPAR BETWEEN RIBS 13 LH AND RH -EXTERNAL SURFACE- (INCLUDING WING-TO-FUSELAGE FITTINGS AND RODS AT RIBS 2 AND 4) (CPCP)	Service	12-Oct-24	57		20-Jun-25
DVI	571410-DVI-10000-1	LOWER SURFACE PANELS - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON WING CENTER BOX LOWER SKIN PANEL EXTERNAL SURFACE AT JUNCTION WITH REAR SPAR BETWEEN RIB 13 LH AND RIB 13 RH, INCLUDING WING TO FUSELAGE FITTING AT RIB 2 AND FITTING AND ROD AT RIB 4 (CPCP)	Service	12-Oct-24	57		25-Jun-25
DVI	572210-DVI-10000-1	FRONT SPAR OF WING OUTER BOX - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON WING OUTER BOX FRONT SPAR BETWEEN RIB 13 AND RIB 30, INCLUDING ALL FITTINGS AND BRACKETS FITTED ON THE SPAR (CPCP)	Service	16-Oct-24	57		23-Jun-25
DVI	572220-DVI-10000-1	OUTER WING BOX - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON REAR SPAR BETWEEN RIBS 13 AND 30, INCLUDING ALL FITTINGS AND BRACKETS FITTED ON THE SPAR (CPCP)	Service	30-Dec-24	57		23-Jun-25
DVI	572418-DVI-10000-1	LOWER SURFACE PANELS - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON LOWER SKIN AT JUNCTION WITH REAR SPAR BETWEEN RIBS 13 AND 23 - EXTERNAL SURFACE (CPCP)	Service	6-Oct-24	57		20-Jun-25
DVI	572501-DVI-10000-1	AILERON HINGE FITTINGS ON WING REAR SPAR - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON AILERON HINGE FITTINGS ON WING REAR SPAR AT RIBS 24,27,30 (CPCP)	Service	6-Oct-24	57		18-Jun-25
DVI	576107-DVI-10000-1	AILERON -AILERON TAB HINGES - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON AILERON TAB HINGES (CPCP)	Service	6-Oct-24	57		18-Jun-25

GVI	576109-GVI-10000-1	AILERONS - METALLIC PARTS - GENERAL VISUAL INSPECTION OF EXTERNAL METALLIC ITEMS OF AILERONS AND TABS	Service	4-May-24	57		2-Jun-25	
GVI	ZL-121-GVI-10000-2	FORWARD LOWER FUSELAGE UNDER CARGO/PAX COMPARTMENT - GENERAL VISUAL INSPECTION OF FORWARD LOWER FUSELAGE UNDER CARGO AND PASSENGER COMPARTMENT FROM FR 13 TO FR 19 UPTO STR 14 LH/RH (EWIS) (CPCP)	Service	16-Apr-24	53		7-Jul-25	
GVI	ZL-121-GVI-10010-1	FORWARD LOWER FUSELAGE UNDER CARGO/PAX COMPARTMENT - GENERAL VISUAL INSPECTION OF FORWARD LOWER FUSELAGE UNDER CARGO AND PASSENGER COMPARTMENT FR 13 TO FR 25, INCLUDING UPPER PART OF CREASE BEAM (EWIS) (CPCP)	Service	7-Oct-24	53		8-Jul-25	
GVI	ZL-133-GVI-10000-1	PRESSURIZED ZONE BETWEEN MLG WELL/CAB.FLOOR - GENERAL VISUAL INSPECTION OF PRESSURIZED ZONE BETWEEN MAIN LANDING GEAR WHEEL WELL AND CABIN FLOOR FROM FR25 TO FR27 (CPCP)	Service	5-Apr-24	53		7-Jul-25	
GVI	ZL-133-GVI-10010-2	PRESSURIZED ZONE BETWEEN MLG WELL/CAB.FLOOR - GENERAL VISUAL INSPECTION OF PRESSURIZED ZONE BETWEEN MAIN LANDING GEAR WHEEL WELL AND CABIN FLOOR FROM FR25 TO FR27, INCLUDING UPPER PART OF CREASE BEAM (CPCP)	Service	14-Oct-24	53		7-Jul-25	
GVI	ZL-141-GVI-10000-2	AFT LOWER FUSELAGE SECTION FR27 TO FR33 - GENERAL VISUAL INSPECTION OF AFT LOWER FUSELAGE SECTION, INCLUDING UPPER PART OF CREASE BEAM (EWIS) (CPCP)	Service	4-Nov-24	53		15-Jul-25	
GVI	ZL-141-GVI-10030-4	AFT LOWER FUSELAGE SECTION FR33 TO FR44 - GENERAL VISUAL INSPECTION OF AFT LOWER FUSELAGE SECTION UP TO STR14 LH/RH (EWIS) (CPCP)	Service	12-Apr-24	53		16-Jul-25	
GVI	ZL-211-GVI-10020-1	FLIGHT COMPARTMENT - GENERAL VISUAL INSPECTION OF FLIGHT COMPARTMENT (EWIS)	Service	4-Nov-24	50		3-Jul-25	
GVI	ZL-255-GVI-10000-1	GALLEY AND AFT PAX COMPARTMENT END (LH) - GENERAL VISUAL INSPECTION OF GALLEY AND AFT PASSENGER COMPARTMENT END (LH SIDE)	Service	6-Oct-24	53		14-Jul-25	
GVI	ZL-513-GVI-10010-1	LEFT WING INTERMEDIATE LEADING EDGE - GENERAL VISUAL INSPECTION OF INTERMEDIATE LEADING EDGE COMPARTMENT	Service	6-Oct-24	57		5-Jun-25	
GVI	ZL-515-GVI-10010-1	LEFT WING OUTBOARD LEADING EDGE - GENERAL VISUAL INSPECTION OF OUTBOARD LEADING EDGE COMPARTMENT	Service	6-Oct-24	57		5-Jun-25	
GVI	ZL-521-GVI-10000-1	CENTER WING BOX AND FUEL TANKS - GENERAL VISUAL INSPECTION OF CENTER WING BOX COMPARTMENT AND INBOARD / OUTBOARD FUEL TANKS. NOTE: IN PARTICULAR - INSPECT RIB 4 FOR FUEL LEAKAGE, - INSPECT DRAIN PIPING (CPCP)	Service	6-Nov-24	57		8-Jun-25	
GVI	ZL-530-GVI-10000-1	LEFT WING TRAILING EDGE AND REAR SPAR - GENERAL VISUAL INSPECTION OF WING TRAILING EDGE AND REAR SPAR (EXTERNAL SURFACE)	Service	24-Dec-23	57		11-Jun-25	
GVI	ZL-531-GVI-10000-2	LEFT WING INBOARD TRAILING EDGE - GENERAL VISUAL INSPECTION OF INBOARD TRAILING EDGE AND REAR SPAR. NOTE: INCLUDING HINGED ACCESS PANELS. (CPCP)	Service	24-Dec-23	57		11-Jun-25	
GVI	ZL-532-GVI-10000-2	LEFT WING INTERMEDIATE TRAILING EDGE - GENERAL VISUAL INSPECTION OF INTERMEDIATE TRAILING EDGE AND REAR SPAR. NOTE: INCLUDING HINGED ACCESS PANELS. (CPCP)	Service	24-Dec-23	57		11-Jun-25	
GVI	ZL-533-GVI-10000-1	LEFT WING OUTBOARD TRAILING EDGE - GENERAL VISUAL INSPECTION OF OUTBOARD TRAILING EDGE	Service	24-Dec-23	57		13-Jun-25	
GVI	ZL-540-GVI-10000-1	LEFT WING CONTROL SURFACES AND FAIRINGS - GENERAL VISUAL INSPECTION OF CONTROL SURFACES UPPER AND LOWER PARTS INCLUDING: FLAPS, SPOILER, AILERON, TAB, AND FAIRINGS	Service	24-Dec-23	27		22-Jun-25	
GVI	ZL-544-GVI-10010-1	LEFT WING AILERON - GENERAL VISUAL INSPECTION OF AILERON (CPCP)	Service	6-Oct-24	27		18-Jun-25	
GVI	ZL-613-GVI-10010-1	RIGHT WING INTERMEDIATE LEADING EDGE - GENERAL VISUAL INSPECTION OF INTERMEDIATE LEADING EDGE COMPARTMENT	Service	6-Oct-24	57		5-Jun-25	
GVI	ZL-615-GVI-10010-1	RIGHT WING OUTBOARD LEADING EDGE - GENERAL VISUAL INSPECTION OF OUTBOARD LEADING EDGE COMPARTMENT	Service	6-Oct-24	57		5-Jun-25	
GVI	ZL-630-GVI-10000-1	RIGHT WING TRAILING EDGE AND REAR SPAR - GENERAL VISUAL INSPECTION OF WING TRAILING EDGE AND REAR SPAR (EXTERNAL SURFACE)	Service	28-Apr-24	57		11-Jun-25	

GVI	ZL-631-GVI-10000-2	RIGHT WING INBOARD TRAILING EDGE - GENERAL VISUAL INSPECTION OF INBOARD TRAILING EDGE AND REAR SPAR. NOTE: INCLUDING HINGED ACCESS PANELS. (CPCP)	Service	23-Dec-23	57		11-Jun-25	
GVI	ZL-632-GVI-10000-2	RIGHT WING INTERMEDIATE TRAILING EDGE - GENERAL VISUAL INSPECTION OF INTERMEDIATE TRAILING EDGE AND REAR SPAR. NOTE: INCLUDING HINGED ACCESS PANELS. (CPCP)	Service	23-Dec-23	57		11-Jun-25	
GVI	ZL-640-GVI-10000-1	RIGHT WING CONTROL SURFACES AND FAIRINGS - GENERAL VISUAL INSPECTION OF CONTROL SURFACES UPPER AND LOWER PARTS INCLUDING: AND FAIRINGS - GENERAL VISUAL INSPECTION OF CONTROL SURFACES UPPER AND LOWER PARTS INCLUDING: FLAPS, SPOILER, AILERON, TAB, , AND FAIRINGS	Service	23-Dec-23	27		22-Jun-25	
GVI	ZL-644-GVI-10010-1	RIGHT WING AILERON - GENERAL VISUAL INSPECTION OF AILERON (CPCP)	Service	30-Sep-24	27		18-Jun-25	
LUB	122227-LUB-10010-1	DETENT LEVERS OF SPOILERS CONTROL - CLEANING AND LUBRICATION OF CLUTCH MECHANISM (DETENT LEVER)	Service	16-Jun-25	12		29-May-25	
DVI	528100-DVI-10000-1	MAIN LANDING GEAR FOLDING DOORS - DETAILED VISUAL INSPECTION OF MAIN LANDING GEAR FOLDING DOOR HINGESAND GEAR DOORS ATTACHMENT DEVICES ON THE FUSELAGE FOR CONDITION	Service	16-Jul-25	52		22-Jul-25	
LUB	122232-LUB-10000-2	MAIN LANDING GEAR UPLOCK BOX - LUBRICATION AND CLEANING OF MAIN LANDING GEAR UPLOCK BOXES	Service	1-Aug-25	12		29-May-25	
LUB	122232-LUB-10010-2	NOSE LANDING GEAR UPLOCK BOX - LUBRICATION AND CLEANING OF NOSE LANDING GEAR UPLOCK BOX	Service	1-Aug-25	12		29-May-25	
DVI	531702-DVI-10000-1	NOSE LANDING GEAR TRUNNION LEG - DETAILED VISUAL INSPECTION FOR CORROSION DETECTION ON LH AND RH HINGE FITTINGS OF NOSE LANDING GEAR TRUNNION LEG AND DRAG BRACE PANEL	Service	5-Aug-25	53		11-Jul-25	
DVI	521100-DVI-10010-1	AIRSTAIR DOOR (LH AFT) - DETAILED VISUAL INSPECTION OF PAX DOOR FOLDING STEP UNDERLYING STRUCTURE	Service	4-Sep-25	52		23-Jul-25	
FUT	521100-FUT-10010-1	AIRSTAIR DOOR (LH AFT) - FUNCTIONAL CHECK OF PAX DOOR FOLDING STEP LOCKING MECHANISM	Service	4-Sep-25	52		23-Jul-25	
GVI	ZL-210-GVI-10000-1	FLIGHT AND FORWARD AVIONICS COMPARTMENT - GENERAL VISUAL INSPECTION OF FLIGHT AND FORWARD AVIONICS COMPARTMENT FROM FR1 TO FR13 (INTERNAL FUSELAGE). NOTE : PAY PARTICULAR ATTENTION TO COCKPIT/ CARGO COMPARTMENT ANTI-SMOKE DOOR OR TO COCKPIT REINFORCED DOOR (IF INSTALLED) FOR GENERAL CONDITION AND TO VENTING AREA FOR OBSTRUCTION	Service	4-Sep-25	50		11-Jul-25	
GVI	ZL-220-GVI-10000-1	FWD CARGO COMPARTMENT - GENERAL VISUAL INSPECTION OF FORWARD CARGO COMPARTMENT (INTERNAL FUSELAGE)	Service	4-Sep-25	50		3-Jul-25	
GVI	ZL-610-GVI-10000-1	RIGHT WING LEADING EDGE AND WING TIP - GENERAL VISUAL INSPECTION OF WING LEADING EDGE AND WING TIP	Service	23-Dec-25	57		5-Jun-25	