The engine was removed because the engineers heard a grinding noise when engine was in idle.
Upon boroscope all disks were fine with no damage.
Suspect the bleed valve is detached. Engine has to go to shop for repair.

ASKING PRICE : 50.000 $US