



1. Engines.
  - a. Engine #1 will be ESN V0011 as shown on the Spec. Engine #2, ESN V0106, will be replaced, swapped with ESN V0026.
  - b. The replacement engine will be serviceable within one month, and have approximately the same LLP cycles remaining to lowest LLP.
  - c. See attached for ESN V0026: AD Status, LLP Status, TCs Status.
  
2. C1 check due January 2026
  - a. the aircraft was parked in Nov./2025. This C1 check was not done.
  - b. Waiting on the technical team to respond to your questions re. work scope or other estimate of the tasks required and cost estimate, including suggestions on local MROs.